




Material List

NO.	Parts	Material
1	Body	FC200
2	Bonnet	FC200
3	Stuffing box	FC200
4	Disc	FC200
5	Handwheel	FC200
6	Valve seat of body	CAC406/SCS2
7	Valve seat of disc	CAC406/SCS2
8	Screwed piece	CAC406(BC6)
9	Guide bush	CAC406(BC6)
10	Guide bush	CAC406(BC6)
11	Packing gland	CAC406(BC6)
12	Indicator	CAC406(BC6)
13	Indicator plate	C2801
14	Stem	C3771/SUS410
15	Stud bolt	SS400
	Hex. Head bolt	
16	Stud bolt	SS400
17	Stud bolt	SS400
18	Taper pin with thread	SUS403
19	Hex. nut	SS400
20	Hex. nut	SS400
21	Hex. nut	SS400
22	Hex. nut	C3604
23	Hex. nut	SS400
24	Machine screw	C2700
25	Split pin	C2600
26	Packing gland	GRAPHITE
27	Gasket	NON ASBESTOS
28	Gasket	NON ASBESTOS
29	Name plate	C2801